



## *Glendale Center Retail Building: Vertical Drain Line Rehabilitation*

Location: Glendale, California

### Situation:

Branch pipe lines from the urinals were experiencing low flow because of buildup and corrosion. The cast iron system consists of 170 feet of pipes with a 4" diameter and 24 feet of 2" branch lines.

### Solution:

Nu Flow cleaned and rehabilitated all 14 floors of the vertical drain line with their structural liner. Thanks to Nu Flow's no-dig technology, work took one week with minimal disruption to tenants, compared to a three week destructive job for traditional repairs and re-piping.

