



Las Flores Tower Condominium: Drain and Potable Rehabilitation

Location: Coronado Island, California

Situation:

Part of the 10" cast iron mainline for Las Flores Tower was missing. A traditional, costly re-pipe would have caused destruction to the lobby, driveway and street. The copper hot recirculation lines and vertical cast iron storm drains experienced corrosion and leaks.

Solution:

Nu Flow cleaned and lined all three 36-year-old pipe systems by accessing the existing connection points on the roof and inside the parking garage. The mainline and storm drain lines were lined with our Pull-in-Place structural lining and the potable system was lined with our blown-in epoxy coating.

