



## ***General Atomics: Sanitary Drain Line System Rehabilitation***

Location: San Diego, California

### **Situation:**

Sanitary drain line had reduced water flow and backups because of cracking, root intrusions and weakened joints. The system consists of 6" clay pipe connected to 4" PVC pipe, beneath a layer asphalt.

### **Solution:**

The pipe is below an entrance to the building, so Nu Flow's trenchless technology prevented disruption to the office's normal operations. Nu Flow cleaned the pipe system, restoring flow, and then installed our structural drain liner to prevent future problems.

