



## ***125 Broad Street Office Building: HVAC Plumbing Riser Rehabilitation***

Location: 125 Broad Street, Lower Manhattan, New York

### **Situation:**

Chronic failure and leaks were occurring in the skyscraper's black iron heating and cooling system. The HVAC risers consisted of 7,200 feet of 1 1/2" to 4" in diameter pipes.

### **Solution:**

The pipe system was cleaned and coated with epoxy to block the leaks and prevent future corrosion. Nu Flow saved the customer millions of dollars in reconstruction and asbestos abatement costs, all while not disrupting normal operations inside the 40-story office building.

