



## *Delta Technical Operations Center: Drain Rehabilitation*

Location: Atlanta, Georgia

### Situation:

Heavy corrosion was causing corrosion and leaks in the kitchen's cast iron floor drains and horizontal runs under the kitchen floor. The customer did not want to close the kitchen and tear up the floor to replace the failing pipes.

### Solution:

Nu Flow cleaned the pipe system and used our no-dig Spot Repair process to cover leaks and cracks. Nu Flow saved the customer money, time and hassle by offering a trenchless solution to failing drain systems.

