



Liquefied Natural Gas Plant: Potable System Rehabilitation

Location: Baja California, Mexico

Situation:

A potable filtration line at a liquefied natural gas plant experienced constant failure and leaks due to the effects of purified water corrosion. The carbon steel pipes are organized in a maze-like pattern across the ceiling, which made them challenging to access.

Solution:

Nu Flow cleaned the potable system and then lined it using our patented blown-in epoxy coating, which created a thin, protective coating that will prevent future problems. This eco-friendly process means less mess, less hassle and less cost for the customer.

