



## First Avenue Apartments: Sanitary Drain System Rehabilitation

Location: San Diego, California

### Situation:

The aged sanitary waste system, located 6 feet beneath the bottom floor apartments, was so heavily corroded that it caused back-ups and floods. The customer spent a lot of time and money on repairs, so they looked for an effective, non-destructive, long-term solution.

### Solution:

Nu Flow offered the ideal solution for the customer. The corrosion build-up had reduced the sanitary pipes' diameters by 75% but our innovative technology restored the diameters back to their original size. Nu Flow's no-dig structural liner was also about 40% cheaper than a re-pipe.

