



## Grossmont Shopping Center: Lateral Sewer Line Rehabilitation

Location: La Mesa, California

### Situation:

The cast iron sewer line experienced clogging and backups as a result of corrosion. The lateral sewer line includes 4" cast iron pipe installed in 1961 and is located under the Barnes & Noble sales floor and the Starbucks.

### Solution:

Nu Flow was able to clear the corrosion and line the sewer system using our no-dig technology. The aged pipes were returned to their original inside diameter, and the structural liner left inside the host pipes will prevent future problems.

