



**Horseshoe Adventure Park Mini Golf Course: Waterfall Drain Pipe Rehabilitation**

Location: Barrie, Ontario, Canada

**Situation:**

When the miniature golf course was built, the owners noticed signs of a leak coming from the waterfall pipe. The corrugated hose was 30 feet long with a 6” diameter, located under the course.

**Solution:**

The Adventure Park was one week away from its grand opening, so traditional repair was not an option, since it would involve digging up the pipes and harming the landscape. Nu Flow’s no-dig structural liner was the perfect solution and the liner installed before the grand opening.

