



Kewaunee Nuclear Power Plant: Underground Drain Rehabilitation

Location: Carlton, Wisconsin

Situation:

Part of a 6" diameter drain pipe encased in concrete was leaking 10 feet under a concrete structure. Breaking through the concrete to access the pipe was not an option.

Solution:

Nu Flow rehabilitated the leaking pipe with our Pull-in-Place structural liner and created a seamless pipe inside the host pipe without disrupting the plant's normal operations. Nu Flow contracted a scuba diver to work at the discharge point below the waterline in Lake Michigan.

