



La Princesa Tower Condominiums: Drain Stack Rehabilitation

Location: Coronado Island, California

Situation:

The 35-year-old kitchen drain pipes in the 15-story beach front condominium were clogging, cracking and leaking. The kitchen stacks are located inside walls and ceilings and consist of 4" cast iron pipes.

Solution:

Nu Flow cleaned and descaled the pipes back to their original diameter. We lined all of the kitchen risers in the 135-unit condominium with our patented Pull-in-Place structural liner without having to tear out walls, floors or ceilings that would have been necessary in a traditional re-pipe project.

