



## Lee County Jail: Sanitary Drain System Rehabilitation

Location: Fort Myers, Florida

### Situation:

4", 6" and 8" diameter cast iron sewer drain pipes under the slabs in half of the 5-story jail were corroded, causing back-ups and limited water flow.

### Solution:

Digging through the foundation was not an option, because the facility had to have the sanitary system operational and the jail was at 94% capacity with no room to move the inmates. Nu Flow's patented Pull-in-Place structural liner was inserted without destruction or disruption.

