



One America Plaza Office Building: Drain and Vent Line Rehabilitation

Location: Downtown San Diego, California

Situation:

Three separate segments of 19-year-old 6" cast iron vent line were failing due to corrosion and scale flakes in the system. The drain and vent lines are located behind finished tenant spaces and walls.

Solution:

Nu Flow's patented Pull-in-Place structural liner was installed, saving the customer from costly and disruptive repairs. Nu Flow's work did not interfere with the office building's operations and our structural liner is a long-term solution against future vent system problems.

