



## *Palm Place Condominium: Sanitary Drain Stack Rehabilitation*

Location: Sarasota, Florida

### Situation:

The six-story building has sanitary drain stacks that consist of 360 feet of 3" and 720 feet of 4" cast iron pipe. The 28-year-old stacks were failing due to heavy corrosion and scale buildup.

### Solution:

Nu Flow cleaned and retrofitted the sanitary drain stacks with our seamless, protective liner. A repipe could not be considered as an option because of the destruction it would cause. Nu Flow's solution did not cause destruction of the building or disruption to residents.

