



San Diego 27-Story Office Building: Storm Drain Stack Rehabilitation

Location: San Diego, California

Situation:

The aged cast iron storm drains in this commercial office building had scale build-up and leaked inside the building. The customer needed a long-term repair method that would not cause destruction or disruption to the busy offices inside the skyscraper.

Solution:

Nu Flow's no-dig technology was chosen because the customer did not want to create a messy work environment for tenants or displace them while the repair was being performed. Nu Flow installed our Pull-in-Place structural liner to cover all cracks and prevent future failures from occurring.

