



Sarasota County: Sanitary Drain Line Rehabilitation

Location: Sarasota County, Florida

Situation:

The county's sanitary drain system, primarily 6" diameter clay pipes, experienced rainwater infiltration through broken and cracked pipe joints. The county resorted to hauling the excess wastewater to relieve overloaded pump stations, incurring unnecessary expenses and overtime.

Solution:

Nu Flow retrofitted the lateral lines connected to the city main with our Pull-in-Place structural drain liner. Our lateral connection liner (LCL) rehabilitated the weakest point in the sewer mains and provided the county with a significant return on investment, preventing further infiltration.

