



St. George's Church: Sanitary Drain Line Rehabilitation

Location: Oshawa, Ontario, Canada

Situation:

172 feet of aged sanitary drain line that extends the church to the main sewer line was experiencing backups due to root intrusion.

Solution:

Nu Flow first cleaned the drain system to remove the roots and restore flow capacity, then Nu Flow retrofitted the pipes with our trenchless, Pull-in-Place structural liner. Nu Flow's trenchless solution preserved the historic church.

