



## Temple Emanu-El: Roof Drain System Rehabilitation

Location: New York, New York

### Situation:

The 10 roof drains encased in concrete pillars were rotten, had leaks and could have destroyed the historical temple from within. The roof drains run through 12-story columns in the middle of the Synagogue.

### Solution:

Nu Flow's trenchless technology preserved the historical temple and the interior columns, causing minimal disruption to the temple's normal operations. Nu Flow's Pull-in-Place structural liner created a new pipe within the existing host pipes, protecting the drain system from future problems.

