



## ***York University Glendon Campus Cafeteria: Drain System Rehabilitation***

Location: Toronto, Canada

### **Situation:**

The cafeteria's 24-year-old 4" cast iron dishwasher drain pipe system experienced severe corrosion, leaks and low flow from heavy scale build-up throughout the years. The customer was sick of the pipe system failures but did not want the mess and disruption from a re-pipe.

### **Solution:**

Nu Flow's "high temperature" epoxy accommodated the 140-degrees dishwasher water. Our patented Pull-in-Place structural liner was installed using existing access points, which prevented the need to dig up the kitchen. This liner protects the drain lines from future failures, including leaks.

